

DIGITAL MULTIMETER

# CE FE EMC LVD ROHS &

**Table of Contents** 

2. Safety note .....

3-1. Product illustration .....

3-3. LCD display ......

4.Specification .....

3-2. Functional push button ........

4-1. General Specification .......

4-2. Electrical Specification .....

5-2. Resistance measurement ....

5-3. Diode & Continuity check .......... 5-4. Frequency Measurement ......

5-6. DC/AC 10A measurement ......

5-7. Non contact voltage test .......

6-1. Replacing the battery .......

6-2. Replacing the fuse ........

6. Maintenance ......

5-5. DC/AC µA or mA measurement ......

5. Measurement operation ......

3. Explanation of Controls and Indicators ..........

5-1. DC voltage & AC voltage measurement ......10

1. Introduction .....

## 1. Introduction

This instrument is a handheld and battery operated Digital Multi Meter (DMM) with multi-function. This Meter is designed to meet IEC61010-1 & CAT II 600V over voltage category and double insulation. The meter with holster that is giving the main body, though downsized, high resistance against the shock of a drop. This operating instruction covers information on safety and caution. Please read relevant information carefully and observe all the warnings and note strictly. The DMM as general measurement tool and widely used in the school, laboratory, factory and other social field. 2. Safety note

# Marning

..... 7- 10


.....13-14

To avoid possible electric shock or personal injury and to avoid possible damage to the meter or to the equipment under test, adhere to the following rule:

- \* Do not apply more than the rated voltage, of marked on the meter, between the input terminal and grounding terminal. ★ Do not apply voltage between COM and OHM terminal, in
- \* Do not measure current with test lead inserted into voltage or OHM terminal. \* Do not expose the instrument to the direct sun light,
- extreme temperature and humidity or dew full.  $\textcolor{red}{\bigstar} \hspace{0.2cm} \textbf{Inspect the test lead for damaged insulation or exposed}$
- \* Before measuring current, check the Meter's fuses and turn off power to the circuit before connecting the meter to the circuit.

\* Disconnect circuit power and discharge all high voltage capacitors before testing continuity, diode, resistance, capacitance or current.

### 3. Explanation of controls and indicators 3-1. Meter illustration



1. LCD display 2. "FUNC" Push button

- 3. "BACK LIGHT" push button and "HOLD" push button 4. Rotary Switch (Knob)
- 5. "V/Ω/HZ/uA/mA" Input terminal 6. "COM" input terminal
- 7. "10A" input terminal 8. Non-contact voltage sensing area (top of instrument)

3


### 3-2. Functional push button

Push button	Function	
FUNC	<b>"FUNC"</b> key is the function select key that acts with trigger. Use the key as switch of DC/AC current, Diode.	
HOLD	Press "HOLD * " to enter and exit the hold mode in any mode. That act with trigger. "HOLD * " This key is used control Backlight. This key is act with trigger. When press and hold	

the key over 2 sec, will enable Backlight.

Press the key again, the backlight will disable.

### 3-3.Display indicators



### Meaning Indicator DC voltage or current AC voltage or current $\sim$ \* Diode Data hold Low battery indicator ΜΚΩ $\Omega$ , $K\Omega$ , $M\Omega$ is unit of resistance mV ,V is unit of voltage μΑ, mΑ, Α is unit of current Indicate negative reading

### 4. Specification

## 4-1. General Specification

\* Auto ranging DMM , that full scale is 2000 counts

6-3. Cleaning and Decontamination .....

- \* Over load protection: Used the PTC protection circuit for Resistance, frequency measurement for. \* DATA HOLD function
- ★ Back Light
- ★ Low battery indication
- \* Auto Power- OFF: If the meter is idle for 15 minutes (idle time), the meter automatically turns the power off. After auto power-off, pushing any of the push button or changing the rotary switch can turn on the meter again.

(1) After auto power off in the AC mode, if changing the rotary switch to the DC mode the Re-power on if disabled (2) The meter enters sleep mode after auto, power off. If mode, the auto power off function is disabled.

- ★ Operating temperature & Humidity: 0 ~ 40°C (32 ~ 104 °F) & < 80% RH
- \* Storage temperature & Humidity: -10 ~ 50°C (14 ~ 122 °F) & <70%RH
- ★ Power Supply: 9V Battery (6F22 or 1604A Type) x 1pc. ★ Safety Class: IEC 61010-1, CAT II 600V.
- **★** Dimension(L x W x H) & Weight: 138 x 68 x 30mm, Approx.

## 4.1.1 Accessary:

1. User's Manual	1p
2. Test Lead	1se
3. 9V Battery	1 p
6	

### **4-2. Electrical Specification** (at 23±5°C; <75% RH) 4.2.1 DC Voltage

	Range	Resolution	Accuracy
	200mV	0.1 mV	
	2V	1mV	±(0.5% rdg + 2dgt)
	20V	0.01V	±(0.5% rag + 2agt)
	200V	0.1V	
	600V	1V	±(0.8% rdg + 2dgt)

4.2.2 AC Voltage

Range	Resolution	Accuracy
2V (40Hz-400Hz)	0.001V	
20V (40Hz-400Hz)	0.01V	±(0.9% rdg + 3dgt)
200V (40Hz-400Hz)	0.1V	
600V (40Hz-200Hz)	1V	±(1.2%)rdg + 3dgt

## 4.2.3 Resistance

Range	Resolution	Accuracy
200Ω	0.1Ω	
2kΩ	0.001kΩ	± (0.8% rdg + 2dgt)
20kΩ	0.01kΩ	
200kΩ	0.1 kΩ	
2ΜΩ	0.001ΜΩ	± (1.0% rdg + 2dgt)
20ΜΩ	0.01ΜΩ	
	7	

## 4.2.4 Diode check

Note international Electrical Symbol.

all the warnings and note strictly.

⚠ Dangerous Voltage

AC Alternating curi

DC (Direct Current)

**≂** AC or DC

This instrument is a handheld and battery operated Digital Multi

Meter (DMM) with multi-function. This Meter is designed to meet IEC61010-1 & CAT II 600V over voltage category and double

insulation. The meter with holster that is giving the main body, though downsized, high resistance against the shock of a drop.

The DMM as general measurement tool and widely used in the

📥 Ground

Fuse

Double insulation

school, laboratory, factory and other social field.

Measurement category (over voltage category):

This instrument is meet the safety condition of CAT II. The

equipment is used for measurement in building facilities. Examples are measurements on distribution boards, circuit

breaker and industrial equipment located in fixed facilities, as a

2

This operating instruction covers information on safety and caution. Please read relevant information carefully and observe

Function Will display the forward drop voltage.	

# 4.2.5 Continuity

01))	will buzzer is sounded.	
* Open voltage: about 0.5V		
4.2.6 DC Current		
Range	Resolution	Accuracy

Range	Resolution	Accuracy
200μΑ	0.1μΑ	
2000μΑ	1μΑ	
20mA	0.01mA	± (1.5% rdg + 3dgt)
200mA	0.1 m A	
10A	0.01 A	
* 0		

\* Over Load protection: use the fuse (F250mA) at  $\mu$ A /mA range, and use the fuse(F10A) at 10A range. \* Max input current:: 250mA at 'mA' input terminal and 10A at '10A' input

terminal.

4.2.8 AC Current [40Hz-400Hz]				
Range	Resolution	Accuracy		
200μΑ	0.1μΑ			
2000μΑ	1μΑ			
20mA	0.01 m A	(1.5% rdg + 4dgt)		
200mA	0.1 mA			
10A	0.01 A			

\* Over Load protection: use the fuse (F250mA) at µA /mA range,and use the fuse(F10A) at 10A range.

\* Max input current: 250mA at 'mA' input terminal and 10A at '10A' input terminal...

\* Frequency response: 40~400Hz

# 4 2 8 Frequency

4.2.6 Frequency				
	Range	Resolution	Accuracy	
	200kHz	0.1 KHz	± (1.5%rdg+5dgt	
*Sensitivity: 0.8V				

To avoid harms to you or damage to the meter from electric shock. Please do not attempt to measure voltage higher than DC/AC 1000V although readings may be obtained. The DC voltage range are 200.0mV, 2.000V, 20.00V, 200.0V and 600V and then. The AC voltage ranges are 2.000V, 20.00V, 200.0V and 600V. To measure DC or AC voltage:

(1) Insert the red test lead into the "V $\Omega$ " input terminal and the black test lead into the COM terminal. (2) Set the rotary switch to DC or AC range.

5. Measurement operation

5-1 DC & AC voltage measurement

(3) Connect the test lead across with the object under testing. The measured value will be show on the LCD display. When DC or AC voltage measurement has been completed,

the circuit under testing.

disconnect the connection between the testing lead and

10

### 5-2 Resistance measurement

The resistance range are:  $200.0\Omega$ , 2.000 K $\Omega$ , 20.00 K $\Omega$ , 200.0 K $\Omega$ ,

(1) Insert the red test lead into the "  $\,$  V $\Omega$ " terminal and the black test lead into the COM terminal.

(2) Set the rotary switch to proper resistance range.. (3) Connect the test lead across with the object under testing. The measured value will be show on the LCD display.

\* The test lead can add  $0.1\Omega$  to  $0.2\Omega$  of error to resistance measurement. To obtain precision reading in low-resistance measurement, that is the range of  $200.0\Omega$ , short the input terminal before measuring. In this time,

the contact resistance displayed on the LCD. You can subtract the contact resistance value from the measured value.

\* For high-resistance measurement (>10MQ), it is normal taking several second to obtain stable reading. \* The LCD display "OL" indicating open-circuit for the

tested resistor or the resistor value is higher than the maximum range of the meter. 5-3 Diode/Continuity check

## 5.3.1 Diode

(1) Set the rotary switch to "→ •••)" position. First time, default mode is diode check mode. You can enter the continuity check mode by the "FUNC" Key. (2) insert the red test lead into the "V  $\Omega$  " terminal and the black test lead into the "COM" terminal.

11

(3) Use the diode test mode to check diodes, transistors and other semiconductor device. In the diode test mode sends a current through the semiconductor junction, and the measure the voltage drop across the junction. A good silicon junction drop between 0.5V and 0.8V.

(4) For forward voltage drop reading on any semiconductor component, place the red test lead on the component anode and place the black test lead on the component cathode. The measured value show on the

(5) Reverse the test lead and measure the voltage across

- the diode again. \* If diode is good, the display shows "OL".
- ★ If diode is shorted, the display shows 0 (zero) in both \* If display shows "OL" in both direction, the diode is

### open. 5.3.2. Continuity Check:

(1) Press the "FUNC" key to enter to the continuity mode. (2) The buzzer sound if the resistance of a circuit under test is less than 100Ω.

# 5-4. Frequency measurement

(1) Set the rotary switch to "Hz" position. (2) Insert the red test lead into the "V $\Omega$ Hz" input terminal and the black test lead into the "COM" terminal.

(3) Connect the test leads across with the circuit under testing. The measured value shown on the LCD display. NOTE: Input signal level must be higher than 0.5V (it is

12

## 5-5. DC/AC µA or mA measurement

DC Current range is 200.0µA/2000µA and 20.00mA,/200.0mA and then 10A range.

AC Current range is 200.0μA/2000μA and 20.00mA,/200.0mA and then 10A range. (1) Turn off power to the circuit. Set the rotary switch to

the proper DC/AC μA or DC/AC mA position. (2) Break the current path to be tested. Connect the red test lead to the more positive side of the break and the black test lead to the more negative side of the break. (3) Turn on power to the circuit. The measured value show

### on the display 5-6. DC/AC 10A measurement

(1) Insert the red test lead into the input terminal marked

(2) The measuring procedure is same as that of 5-5 section.. NOTE: \* For safety's sake, the measuring time for high current

should be ≤ 10 second for each measurement and the interval time between two measurement should be greater than 5 minutes.

\* When current measurement has been completed,

disconnect the connection between the testing lead

### and the circuit under test. 5-7. Non-contact voltage test

Close to the top of the instrument conductor, when the detection of voltage is greater than 90V (RMS), when the instrument close to the conductor, the instrument sensor voltage background light and buzzer alarm sound.

13

(1) Even if there is no indication, the voltage may still exist. Do not rely on non-contact voltage detector to determine whether there is a voltage. The detection operation may be affected by socket design, insulation

thickness and type of different factors. (2) When the input voltage of the input terminal, due to the presence of the induced voltage, the background light may also be bright.

(3) The external environment of the source of interference (such as flash, motor, etc.), may be triggered by non-contact voltage detection.

### 6. Maintenance 6-1. Replace the battery

When meter display 📾 the battery must be replace to maintain normal operation. (1) Disconnect and remove all test probes from any live source and meter.

(2) Open the battery cover on the bottom case by

### (3) Remove old battery and snap new one into battery holder 6-2. Fuse replacement

Replacing the defective fuse should the done according to the following procedure. (1) To avoid electrical shock, remove the test lead and any input signal before opening the bottom case. (2) Open the button case and then remove the defective fuse and insert a new fuse of the same size and rating.

14

(3) Replace the bottom case and reinstall all the screw.

## 6-3.Cleaning and Decontamination

The meter can be cleaned with soft clean cloth to remove any oil, grease or grim. Do not use liquid solvent or

15